Table of Contents

Dedication iii
Preface xvii

Chapter 1: Introduction to NX 8.5

Introduction to NX 8.5 1-2
System Requirements 1-3
Getting Started with NX 1-4
Important Terms and Definitions 1-6
Understanding the Functions of the Mouse Buttons 1-10
Toolbars 1-11
Hot Keys 1-17
Color Scheme 1-17
Dialog Boxes in NX 1-18
Selecting Objects 1-19
Deselecting Objects 1-19
Selecting Objects Using the QuickPick Dialog Box 1-19
Self-Evaluation Test 1-19

Chapter 2: Drawing Sketches for Solid Models

The Sketch task Environment 2-2
Starting NX 8.5 2-2
Starting a New Document in NX 8.5 2-4
Invoking Different NX Environments 2-7
Creating Three Fixed Datum Planes (XC-YC, YC-ZC, XC-ZC) 2-7
Displaying the WCS (Work Coordinate System) 2-8
Creating Sketches 2-9
    Creating Sketches in the Sketch task Environment 2-9
    Creating Sketches in the Modeling Environment 2-15
Sketching Tools 2-15
    Drawing Sketches Using the Profile Tool 2-15
    Using Help Lines to Locate Points 2-19
    Drawing Individual Lines 2-19
    Drawing Arcs 2-19
    Drawing Circles 2-21
    Drawing Rectangles 2-22
    Placing Points 2-24
    Drawing Ellipses or Elliptical Arcs 2-28
    Drawing Conics 2-30
    Drawing Studio Splines 2-31

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Filleting Sketched Entities 2-33
The Drawing Display Tools 2-35
Fitting Entities in the Current Display 2-35
Zooming an Area 2-35
Dynamic Zooming 2-36
Panning Drawings 2-36
Fitting View to Selection 2-37
Restoring the Original Orientation of the Sketching Plane 2-37
Setting Selection Filters in the Sketch task Environment 2-37
Selecting Objects 2-39
Deselecting Objects 2-39
Using Snap Points Options While Sketching 2-39
Deleting Sketched Entities 2-40
Exiting the Sketch task Environment 2-40
Tutorial 1 2-41
Tutorial 2 2-44
Tutorial 3 2-50
Self-Evaluation Test 2-54
Review Questions 2-55
Exercise 1 2-56
Exercise 2 2-56

Chapter 3: Adding Geometric and Dimensional Constraints to Sketches

Constraining Sketches 3-2
Concept of Constrained Sketches 3-2
Under-Constrain 3-2
Fully-Constrain 3-2
Over-Constrain 3-2
Degree of Freedom Arrows 3-3
Dimensioning Sketches 3-4
Locking the Automatically Applied Dimensions of the Sketch 3-4
Applying Horizontal Dimensions 3-5
Applying Vertical Dimensions 3-5
Applying Parallel Dimensions 3-6
Applying Perpendicular Dimensions 3-7
Applying Angular Dimensions 3-8
Applying Diameter Dimensions 3-8
Applying Radius Dimensions 3-9
Applying Perimeter Dimensions 3-10
Applying Dimensions by Using the Inferred Dimensions Tool 3-10
Editing the Dimension Value and Other Parameters 3-11
Animating a Fully-Constrained Sketch 3-12
Measuring the Distance Value between Objects in a Sketch Enhanced 3-13
Measuring the Distance between Two Objects in a Sketch 3-14
Measuring the Projected Distance between Two Objects 3-15

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Measuring the Screen Distance between Two Objects 3-15
Measuring the Length of an Arc or a Line 3-16
Measuring the Angle between Entities 3-16
Measuring the Angle Value Using the By Objects Option 3-16
Measuring the Angle Value Using the By 3 Points Option 3-17
Measuring the Angle Value Using the By Screen Points Option 3-18
Geometric Constraints Enhanced 3-18
Applying Additional Constraints Individually 3-19
Applying Symmetry constraint 3-25
Applying Automatic Constraints to a Sketch 3-25
Controlling Inferred Constraints Settings 3-27
Showing All Constraints in a Sketch 3-28
Showing/Removing Constraints 3-28
Converting a Sketch Entity or Dimension into a Reference Entity or Reference Dimension 3-30
Tutorial 1 3-31
Tutorial 2 3-37
Tutorial 3 3-40
Self-Evaluation Test 3-44
Review Questions 3-44
Exercise 1 3-45
Exercise 2 3-46

Chapter 4: Editing, Extruding, and Revolving Sketches

Editing Sketches 4-2
Trimming Sketched Entities 4-2
Extending Sketched Entities 4-3
Creating a Corner between Sketched Entities 4-4
Offsetting Sketched Entities 4-5
Mirroring Sketched Entities 4-7
Creating Linear Sketch Pattern 4-8
Creating Circular Sketch Pattern 4-9
Copying, Moving, and Rotating Sketched Entities 4-10
Transforming Sketched Entities 4-15
Editing Sketched Entities by Dragging 4-19
Exiting the Sketch task Environment 4-20
Changing the View of the Sketch 4-20
Creating Base Features by Extruding 4-20
Extrude Dialog Box Options 4-21
Creating Solid Revolved Bodies 4-28
Hiding Entities 4-33
Showing Hidden Entities 4-34
Hiding All Entities Using a Single Tool 4-34
Rotating the View of a Model in 3D Space 4-35
Setting Display Modes 4-36

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Tutorial 1 4-36
Tutorial 2 4-39
Tutorial 3 4-43
Self-Evaluation Test 4-46
Review Questions 4-47
Exercise 1 4-48
Exercise 2 4-48

Chapter 5: Working with Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes 5-2
Types of Datum Planes 5-3
Creating Three Fixed (Principle) Datum Planes 5-3
Creating Relative Datum Planes 5-3
Creating Datum Coordinate Systems 5-9
Creating Fixed and Relative Datum Axes 5-13
Other Extrusion Options Enhanced 5-17
Specifying the Boolean Operation 5-17
Specifying Other Extrusion Termination Options 5-19
Projecting External Elements 5-21
Tutorial 1 5-23
Tutorial 2 5-28
Tutorial 3 5-32
Self-Evaluation Test 5-36
Review Questions 5-37
Exercise 1 5-38
Exercise 2 5-38
Exercise 3 5-39

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools 6-2
Creating Holes by Using the Hole Tool 6-2
Creating General Holes 6-3
Creating Drill Size Hole 6-4
Creating Screw Clearance Hole 6-5
Creating Threaded Hole 6-5
Creating Hole Series 6-6
Creating Grooves 6-7
Creating Rectangular Grooves 6-8
Creating Ball End Grooves 6-10
Creating U Grooves 6-11
Creating Slots 6-12
Creating Rectangular Slots 6-12
Creating Ball-End Slots 6-15
Creating U-Slots 6-17
Creating T-Slots 6-19

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Dove-Tail Slots 6-20
Creating Chamfers 6-22
Creating a Chamfer Feature Using the Symmetric Method 6-23
Creating a Chamfer Feature Using the Asymmetric Method 6-25
Creating a Chamfer Feature Using the Offset and Angle Method 6-25
Creating an Edge Blend 6-26
Tutorial 1 6-31
Tutorial 2 6-39
Self-Evaluation Test 6-46
Review Questions 6-47
Exercise 1 6-48
Exercise 2 6-48
Exercise 3 6-49

Chapter 7: Advanced Modeling Tools-II

Advanced Modeling Tools 7-2
Pattern Feature Tool Enhanced 7-2
Creating Linear Pattern 7-2
Creating Circular Pattern 7-8
Creating Polygon Pattern 7-11
Creating Spiral Pattern 7-13
Creating a Pattern Along a Curve 7-14
Creating Reference Pattern 7-17
Creating a Fill Pattern 7-17
Mirror Feature Tool Enhanced 7-20
Sweeping Sketches Along the Guide Curves 7-21
Creating Swept Features Enhanced 7-23
Creating Tubes or Cables 7-26
Creating Threads 7-27
Creating Symbolic Threads 7-28
Creating Detailed Threads 7-31
Creating Shell Features 7-32
Shelling the Entire Solid Body 7-33
Tutorial 1 7-34
Tutorial 2 7-37
Tutorial 3 7-40
Tutorial 4 7-45
Self-Evaluation Test 7-51
Review Questions 7-52
Exercise 1 7-53
Exercise 2 7-53

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Chapter 8: Editing Features and Advanced Modeling Tools-III

Editing Features 8-2
- Editing a Hole Feature 8-2
- Editing the Positioning of a Groove Feature 8-2
- Editing the Positioning of a Slot Feature 8-3
- Editing the Parameters of Features 8-3
- Editing the Parameters of Features with Rollback 8-3
- Editing Sketches of the Sketch-based Features 8-3
- Reordering Features 8-4

Advanced Modeling Tools 8-4
- Creating Boss Features 8-4
- Creating Pocket Features 8-5
- Creating Pad Features 8-9
- Creating Drafts 8-12

Tutorial 1 8-15
Tutorial 2 8-19
Tutorial 3 8-27
Self-Evaluation Test 8-34
Review Questions 8-35
Exercise 1 8-36
Exercise 2 8-37
Exercise 3 8-38

Chapter 9: Assembly Modeling-I

The Assembly Environment 9-2
Invoking the Assembly Environment 9-2
- Invoking the Assembly Environment Using the New Dialog Box 9-2
- Invoking the Assembly Environment in the Current Part File 9-3
- Types of Assembly Design Approaches 9-3

Creating Bottom-up Assemblies 9-4
- Placing Components in the Assembly Environment 9-4
- Changing the Reference Set of a Component 9-7
- Applying Assembly Constraints to Components 9-7
- Points to Remember while Assembling Components 9-17
- Creating a Component Array in an Assembly 9-17
- Replacing a Component in an Assembly 9-20
- Moving a Component in an Assembly 9-21
- Mirroring a Component in an Assembly 9-25
- Modifying a Component in the Assembly File 9-28

Tutorial 1 9-29
Tutorial 2 9-42
Self-Evaluation Test 9-55
Review Questions 9-56
Exercise 1 9-56

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Exercise 2 9-58
Exercise 3 9-61
Exercise 4 9-64

Chapter 10: Assembly Modeling-II

The Top-down Assembly Design Approach 10-2
Creating Components Using the Top-down Assembly Design Approach 10-2
Creating Subassemblies 10-4
Editing Assembly Constraints 10-5
Modifying the Assembly Constraints 10-5
Checking the Interference between the Components of an Assembly 10-6
Checking Interference Using the Simple Interference Tool 10-6
Checking Interference and Clearance Using the Check Clearance Analysis 10-8
Checking Interference Using the Assembly Clearance Method 10-9
Checking Interference and Clearance, and Analyzing Cross-sections of Components Using the View Section Tool 10-15
Creating Exploded Views of an Assembly 10-20
Exploding Views Automatically 10-21
Exploding Views Manually 10-22
Tutorial 1 10-24
Tutorial 2 10-28
Tutorial 3 10-33
Tutorial 4 10-39
Self-Evaluation Test 10-44
Review Questions 10-45
Exercise 1 10-46

Chapter 11: Surface Modeling

Introduction to Surface Modeling 11-2
Invoking the Shape Studio Environment 11-2
Creating an Extruded Surface 11-3
Creating a Revolved Surface 11-3
Creating a Ruled Surface 11-4
Creating a Surface Using the Through Curves Tool 11-6
Creating a Surface Using the Through Curve Mesh Tool 11-8
Creating a Surface Using the Four Point Surface Tool 11-10
Creating a Swoop Surface 11-10
Creating Planar Surfaces from 2D Sketches and Edges of Solid or Surface 11-12
Creating a Transition Surface Using the Transition Tool 11-13
Creating an N-Sided Surface 11-15
Creating a Silhouette Flange Surface 11-18
Extending a Surface Using the Law Extension Tool Enhanced 11-22
Creating a Surface Offset Using the Offset Surface Tool 11-26
Trimming and Extending a Surface Using the Trim and Extend Tool 11-27
Trimming a Sheet by Using the Trimmed Sheet Tool 11-28
Creating a Surface Using the Studio Surface Tool 11-30
Creating a Surface between Two Walls Using the Styled Blend Tool 11-33

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Surfaces Using the Styled Sweep Tool 11-38
Sewing Individual Surfaces into a Single Surface 11-39
Adding Thickness to a Surface 11-40
Adding Drafts Enhanced 11-41
Tutorial 1 11-43
Tutorial 2 11-48
Self-Evaluation Test 11-56
Review Questions 11-56
Exercise 1 11-57
Exercise 2 11-58

Chapter 12: Advanced Surface Modeling

Creating Curves from Bodies 12-2
Creating Intersection Curves 12-2
Creating Section Curves 12-3
Creating Extract Curves Enhanced 12-8
Creating Isoparametric Curves 12-10
Projecting Curves 12-12
Advanced Surface Modeling Tools 12-15
Creating Dart Features 12-15
Creating Emboss Body on a Sheet or Solid Body New 12-17
Creating Face Blend Features 12-18
Creating Soft Blend Features 12-23
Creating Bridge Features 12-26
Tutorial 1 12-27
Tutorial 2 12-38
Tutorial 3 12-47
Self-Evaluation Test 12-59
Review Questions 12-59
Exercise 1 12-60
Exercise 2 12-61

Chapter 13: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Environment 13-2
Invoking the Drafting Environment 13-2
Invoking the Drafting Environment Using the Drawing Template from the New Dialog Box 13-2
Invoking the Drafting Environment in the Current Part File 13-3
Editing the Drawing Sheet Parameters in the Drafting Environment 13-6
Invoking the Drafting Tools 13-6
Types of Drawing Views in NX 13-6
Base View 13-6
Projected View 13-7
Detail View 13-7
Section View 13-7
Auxiliary View 13-7

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Half-Section View 13-7
Revolved Section View 13-7
Break-Out Section View 13-7
Broken View 13-7
Generating Drawing Views 13-8
Generating Views Using the View Creation Wizard Tool Enhanced 13-8
Generating the Base View 13-13
Generating the Orthographic Drawing Views Using the Projected View Tool 13-16
Generating the Detail View Using the Detail View Tool 13-17
Generating Section Views Using the Section View Tool 13-21
Generating the Half Section View Using the Half Section View Tool 13-25
Generating the Revolved Section View 13-26
Generating the Break-Out Section View 13-27
Generating the Broken View 13-28
Manipulating the Drawing Views 13-30
Aligning the Drawing Views Using the Align View Tool Enhanced 13-30
View Boundary 13-32
Displaying the Model Using the Display Sheet Tool 13-34
Inserting a Drawing Sheet Using the New Sheet Tool 13-34
Modifying the Properties of a Generated Drawing View 13-34
Modifying the Scale Value of the Drawing View 13-34
Adding Dimensions to the Drawing Views 13-36
Retrieving Dimensions from the Model 13-36
Adding Dimensions to the Drawing View 13-37
Generating Exploded Views of an Assembly 13-40
Creating Parts List and Associative Balloons 13-40
Creating a Parts List for an Assembly 13-41
Creating Associative Balloons 13-41
Creating a Tabular Note (Title Block) 13-43
Adding Multiline Text to a Drawing Sheet 13-44
Printing Tools 13-45
Print 13-45
Plot 13-46
Tutorial 1 13-47
Tutorial 2 13-52
Tutorial 3 13-58
Self-Evaluation Test 13-65
Review Questions 13-66
Exercise 1 13-67
Exercise 2 13-68

Chapter 14: Synchronous Modeling

Introduction 14-2
Move Face Enhanced 14-2
Pull Face 14-5
Offset Region 14-7

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Replace Face 14-8
Resize Blend 14-9
Reorder Blend 14-9
Resize Chamfer 14-10
Label Chamfer 14-10
Label Notch Blend New 14-11
Resize Face Enhanced 14-11
Delete Face 14-12
Copy Face 14-14
Cut Face 14-15
Paste Face 14-16
Mirror Face 14-17
Pattern Face 14-17
Make Coplanar 14-18
Make Coaxial 14-19
Make Tangent 14-20
Make Symmetric 14-21
Make Parallel 14-22
Make Perpendicular 14-23
Make Fixed 14-24
Make Offset 14-25
Show Related Face 14-26
Linear Dimension 14-26
Angular Dimension 14-28
Radial Dimension 14-29
Shell Body 14-31
Shell Face 14-32
Change Shell Thickness 14-33
Group Face 14-34
Edit Cross Section in History Free Mode 14-34
Edit Cross Section in History Mode 14-36
Tutorial 1 14-36
Tutorial 2 14-42
Self-Evaluation Test 14-51
Review Questions 14-52
Exercise 1 14-53
Exercise 2 14-53

Chapter 15: Sheet Metal Design

The Sheet Metal Module 15-2
Setting the Sheet Metal Part Properties 15-4
Creating the Base feature 15-7
Adding Flanges to a Sheet Metal Part 15-8
Creating Contour Flanges 15-15

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Lofted Flanges 15-16
Adding a Jog to the Sheet 15-17
Bending the Sheet Metal Part 15-18
Unbending the Sheet Metal Part 15-19
Rebending the Sheet Metal Part 15-19
Filleting or Chamfering Corners 15-19
Closing the Corners of a Sheet Metal Part 15-20
Creating Dimples in a Sheet Metal Part 15-24
Creating Louvers in a Sheet Metal Part 15-27
Creating Drawn Cutouts in a Sheet Metal Part 15-28
Creating Beads in a Sheet Metal Part 15-29
Adding Gussets to a Sheet Metal part 15-32
Adding Hems 15-35
Creating a Sheet Metal Part using Solid body 15-39
Converting a Solid Part Into a Sheet Metal Part 15-39
Ripping the Corners of a Solid Part 15-41
Creating the Flat Pattern of a Sheet Metal Part 15-41
    Creating the Flat Pattern 15-41
    Creating the Flat Solid 15-42
    Exporting a Flat Pattern 15-43
Tutorial 1 15-43
Tutorial 2 15-53
Self-Evaluation Test 15-59
Review Questions 15-59
Exercise 1 15-60
Exercise 2 15-62

Index 1

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com